Document ID: 1744006 Page 1 of 3

2009 GMC Truck Sierra - 2WD | Sierra, Silverado (VIN C/K) Service Manual | Engine | Engine Mechanical - 4.8L, 5.3L, 6.0L, 6.2L, or 7.0L | Description and Operation | **Document ID: 1744006** 

## **Base Engine Misfire without Internal Engine Noises**

Cause	Correction
Fuel injector harness connectors are connected to the incorrect fuel injectors/cylinders	Relocate the fuel injector harness connectors, as necessary.
Abnormalities, such as severe cracking, bumps, or missing areas in the accessory drive belt	Replace the drive belt. Refer to <u>Drive</u> <u>Belt Replacement - Accessory</u> .
Abnormalities in the accessory drive system and/or components may cause engine RPM variations and lead to a misfire diagnostic trouble code (DTC). A misfire code may be present without an actual misfire condition.	
Worn, damaged, or mis-aligned accessory drive components or excessive pulley runout	Inspect the components and repair or replace, as required.
May lead to a misfire DTC.	
A misfire code may be present without an actual misfire condition.	
Loose or improperly installed engine flex plate or crankshaft balancer	Repair or replace the flex plate and/or balancer, as required. Refer to Automatic Transmission Flex Plate
A misfire code may be present without an actual misfire condition.	Replacement , or <u>Crankshaft Balancer</u> Replacement .
Restricted exhaust system	Repair or replace, as required.
A severe restriction in the exhaust flow can cause significant loss of engine performance and may set a DTC. Possible causes of restrictions include collapsed or dented pipes or plugged mufflers and/or catalytic converters.	
Improperly installed or damaged vacuum hoses	Repair or replace, as required.
Improper sealing between the intake manifold and cylinder heads or throttle body	Replace the intake manifold, gaskets, cylinder heads, and/or throttle body, as required.
Improperly installed or damaged manifold absolute pressure (MAP) sensor	Repair or replace the MAP sensor, as required.
The sealing grommet of the MAP sensor should not be torn or damaged.	
Worn or loose rocker arms	Replace the valve rocker arms, as required.
The rocker arm bearing end caps and/or needle bearings should be intact and in the proper position.	
Worn or bent pushrods	Replace the pushrods.
© 2012 General Motors Corporat	ibn. All rights reserved.

Document ID: 1744006 Page 2 of 3

Stuck valves	Inspect the top of the pistons for valve contact. If the top of the piston shows valve contact, replace the piston and pin assembly.  Repair or replace, as required.
Carbon buildup on the valve stem can cause the valve to not close properly.	ropair or ropidoo, as roquired.
Excessively worn or mis-aligned timing chain	Replace the timing chain and sprockets, as required.
Worn camshaft lobes	Replace the camshaft and valve lifters.
Excessive oil pressure  A lubrication system with excessive oil pressure may lead to excessive valve lifter pump-up and loss of compression.	Perform an oil pressure test.     Refer to <u>Oil Pressure Diagnosis</u> and <u>Testing</u> .      Repair or replace the oil pump, as required.
Faulty cylinder head gaskets and/or cracking or other damage to the cylinder heads and engine block cooling system passages  Coolant consumption may or may not cause the engine to overheat.	Inspect for spark plugs saturated by coolant. Refer to Spark Plug Inspection.      Inspect the cylinder heads, engine block, and/or head gaskets. Refer to Coolant in Combustion Chamber.      Repair or replace, as required.
Worn piston rings  Oil consumption may or may not cause the engine to misfire.	Inspect the spark plugs for oil deposits. Refer to Spark Plug Inspection.      Inspect the cylinders for a loss of compression. Refer to Engine Compression Test.      Perform cylinder leak down and compression testing to identify the cause. Refer to Cylinder Leakage Test.      Repair or replace, as required.
A damaged crankshaft reluctor wheel  A damaged crankshaft reluctor wheel can result in different symptoms depending on the severity and location of the damage.	Replace the sensor and/or crankshaft, as required.
<ul> <li>Systems with electronic communications, DIS or coil per cylinder, and severe reluctor ring damage may exhibit periodic loss of crankshaft position, stop delivering a signal, and then sync the crankshaft position.</li> <li>Systems with electronic communication, DIS or coil per cylinder, and slight reluctor ring damage may exhibit no loss of crankshaft position and no misfire may occur. However, a</li> </ul>	

Document ID: 1744006 Page 3 of 3

<ul> <li>P0300 DTC may be set.</li> <li>Systems with mechanical communications, high voltage switch, and severe reluctor ring damage may cause additional pulses and effect fuel and spark delivery to the point of generating a P0300 DTC or P0336.</li> </ul>	
Improper operation of the active fuel management system	Repair, as required. Refer to <u>Cylinder</u> Deactivation (Active Fuel Management) <u>System Diagnosis</u> .
Improper operation of the camshaft position (CMP) actuator and/or control system	Repair, as required. Refer to <u>Camshaft</u> <u>Position Actuator and Solenoid Valve</u> <u>Diagnosis and Testing</u> .